

| Model - Required Selections | | N-I/A Series Model Configurator | | | | | | | | | |
|--|--|---|---|---|---|----|----------|-------------------|---------|--------------------------|--|
| N-IDP10S | Differential Pressure Transmitter | | | | | | | | | | |
| N-IAP10S | Absolute Pressure Transmitter | | | | | | | | | | |
| N-IGP10S | Gauge Pressure Transmitter | | | | | | | | | | |
| Output Signal | | | | | | | | | | | |
| T | Digital, 4 to 20 mA HART | | | | | | | | | | |
| Structure Code | | | | | | | | | | | |
| Code | Process Cover | Sensor Material | | | | | | Fill Fluid | | | |
| 22 | 316 ss | 316L ss | | | | | | Silicone | | | |
| Span | | | | | | | | | | | |
| Code | Range | Units | | | | | | | | | |
| B | 200 | inH2O | | | | | | | | | |
| C | 1000 | inH2O | | | | | | | | | |
| D | 300 | psi | | | | | | | | | |
| E | 3000 | psi | | | | | | | | | |
| F | 5000 | psi (Range Code F valid for AP/GP only) | | | | | | | | | |
| Process Connector (football) | | | | | | | | | | | |
| 0 | None (applies to DP only) | | | | | | | | | | |
| Conduit Connection and Housing Material | | | | | | | | | | | |
| 1 | 1/2 NPT, Aluminum Housing | | | | | | | | | | |
| 3 | 1/2 NPT, 316 ss Housing | | | | | | | | | | |
| Electrical Certifications | | | | | | | | | | | |
| AP | ATEX multiple certifications | | | | | | | | | | |
| CP | CSA multiple certifications | | | | | | | | | | |
| FP | FM multiple certifications | | | | | | | | | | |
| ZZ | No certification | | | | | | | | | | |
| Optional Selections | | | | | | | | | | | |
| Optional Digital indicator with Pushbuttons | | | | | | | | | | | |
| -L1 | Digital Display, Pushbuttons and Window Cover | | | | | | | | | | |
| Optional Cleaning and Preparation | | | | | | | | | | | |
| -X1 | Degreased | | | | | | | | | | |
| Optional Bolting for Process Covers | | | | | | | | | | | |
| -B1 | 316 ss Bolts and Nuts (MWP derated to 2175 psi) | | | | | | | | | | |
| -B2 | 17-4 PH ss Bolts and Nuts (no pressure derating) | | | | | | | | | | |
| Optional Electronics Housing Features | | | | | | | | | | | |
| -Z1 | External Zero Adjustment | | | | | | | | | | |
| Miscellaneous Optional Selections | | | | | | | | | | | |
| -K2 | FoxDoc DVD-ROM (instead of "Getting Started" Guide) | | | | | | | | | | |
| -V5 | Vent Screw in side of each Process Cover (-V for DP) | | | | | | | | | | |
| Ultra Supplied Options | | | | | | | | | | | |
| Mounting Bracket | | | | | | | | | | | |
| -UB | Seismic, PN 1000-520-0015T | | | | | | | | | | |
| -UT | Customer Tag | | | | | | | | | | |
| -UV | Vent valve in process ports | | | | | | | | | | |
| -UZ | Other Special Requirements | | | | | | | | | | |
| N-IDP10S | T | 22 | B | 0 | 3 | FP | -L1 - X1 | ECEPC# | -UB -UT | <== Example Model Number | |